


Quelle: Archiv Deutsches Schifffahrtsmuseum



NOT TO BE USED FOR NAVIGATION



WATERS SURROUNDING THE BRITISH ISLANDS MINED AREAS AND SAFE CHANNELS REFERENCE

This chart shows diagrammatically the state of the seas as regards dangerous areas surrounding the British Islands as published in Mine Warnings to Mariners up to and including Mine Warnings to Mariners No 152.

The heavy black lines indicate the boundaries of the areas into which the zones are sub-divided.

- I is the North Sea Zone Area I
- II - - - - - Area II
- III - - - - - Area III
- IV - - - - - Area IV
- V - - - - - Area V
- VI is the English Channel & West Coast of United Kingdom Zone - - - - - English Channel - Northern Portion
- VII - - - - - English Channel - Southern Portion
- VIII - - - - - West Coast of United Kingdom
- IX West Coast of France Spain & Portugal Zone

Areas and channels left white are considered clear of moored mines
 Areas tinted red are considered dangerous owing to the possible existence of moored mines
 Areas hatched and tinted red are known to contain mine fields
 Areas cross hatched red but not tinted contain moored mines which are not dangerous to surface craft, but in which cross anchoring, fishing or using the lead is prohibited.